



# Air Purge Guide for PCME *ElectroDynamic*® Sensors

## Air Purge Fittings

### Standard Fitting (ACCAIR-S)



### Standard Fitting for Insulated Rods (ACCAIR-I)



### Passive/Active Fitting (ACCAIR-P)



### FAPA Fitting (ACCSTB-S-250)

